

ZILKER METRO PARK CLUBHOUSE REHABILITATION PROJECT

November 10, 2020






OPEN HOUSE | November 10, 2020

Meeting Purpose

This meeting will introduce the project team and share more about the rehabilitation plans. The project team will explain the scope and purpose of the renovations, and how these changes will ensure sustained use by Austin residents for generations.

An opportunity to ask questions for clarification or additional information will occur at the end of the presentation.


OPEN HOUSE | November 10, 2020 2



OPEN HOUSE | November 10, 2020 3

Chronology

- 1917 Barton Springs Park given to City of Austin
- 1932 Remainder of Zilker Park, large tract north and west of original gift, given to City of Austin
- 1934 Boy Scout Lodge (now known as Zilker Clubhouse) built by the CWA, CCC
- I934 Lookout Point built by the CCC
- 1940 Addition to north wing built by the NYA, for use as a caretaker's residence
- 1956 Paved terrace added to the east of the Clubhouse, built by the Jaycees
- 1963 PARD facilities officially integrated
- 1994 New restrooms added north of main room, accessible parking and entry route
- 1997 Clubhouse and Point listed on National Register under the Zilker Park NRHD
- 2006 HABS drawings and documentation completed by UT SOA
- 2012 Zilker Park Cultural Landscape Report completed by UT SOA MSHP student



Boy Scout Clubhouse construction, ca. 1934, Austin History Center



LEGEND

1	1934	

1940

1994





Lookout Point construction, 1934, Austin History Center



Lookout Point, 1934, Austin History Center



Lookout Point, 1937, Austin History Center



Lookout Point, 2020



Zilker Clubhouse, ca. 1940s, Foster, William Hague. University of North Texas Libraries, The Portal to Texas History, https://texashistory.unt.edu; crediting Austin Presbyterian Theological Seminary




Photo courtesy gypc.girl.photography

Scope Summary

- Preservation and restoration of building
- Programmatic priority for event use
- Restore infilled original windows and doors
- Restore the connection of main hall to cottage

Modest formalizing elements to parking

Landscape plan, drip irrigation

Wayfinding and interpretive signage

Study HVAC system, water heater relocation, gas service

Replace electrical and data systems, improve lighting

Window and door restoration, roof replacement, masonry cleaning, ironwork restoration

Preliminary Design Report ZILKER CLUBHOUSE Rehabilitation



200 Arnulfo Alonso Way Austin, Texas





View to the south of the Main Room. An interior photograph from the 1940s shows a door opening in the southwest corner, nou infilled. v opening: vetroom








ZILKER CLUBHOUSE Rehabilitation



The caretaker's quarters are conditioned with three window heat pump units, shown in Figure 3. All window units are outdated and inefficient as well as reduce the aesthetics of the yard, which will be updated to be the main entrance of the building. The units are connected via exterior conduit ran outside, further cluttering the outside space. During the site visit, we noted that there are several personal heaters in the caretaker's space, indicating insufficient heating by the window units. Personal heaters are inefficient and increase the electrical load of the building, leading to high electricity bills.



4 | Page



Based on a projected space usage diagram, a preliminary occupant load calculation was prepared.

Contemporary Needs

Building Code Under the 2015 Inte

Building Code Under the 2015 International Building Code, the building is classified as an Assembly-Group A-3 occupancy. The building is assumed to be a Type V-A construction type, in previous permit determinations made by the building officials. The existing building conforms to the allowable height and area limitations for the occupancy group and type of construction classifications.

type of construction classifications. In Assembly occupancies, spaces with an occupant load of more than 49 must have two exits. The exits must be located at a distance apart of not less than half of the larg-est diagonal dimension of the room or area server. The Main Room is subject to the two exit requirement, under current code. Restoring the original entry on the west side of the building will enhance conformance with this requirement, since the two existing exits are both on the east side of the room.

exits are both on the east side of the room. The toilet room, storage and mechanical room functions are considered accessory occu-pancies to the main Assembly occupancies. A one-hour fire-resistance rated corridor is required under the Assembly occupancy, since the building does not have a sprinkler system, but the configuration of the building doesn't appear to have spaces that meet the definition of a corridor. It may be helpful to review the applicability of this require-ment with a building official, as the rehabilitation design is developed. In a preliminary review meeting with the Austin Fire Department plan reviewer, the configuration of the existing fire lane and fire hydrant locations were discussed. Based on their understanding of the preliminary project scope, the AFD indicated that upgrades to the fire access land and fire hydrant locations would not be required for the Rabibilitation project. We also reviewed the requirements for plumbing fixture counts within current code.

We also reviewed the requirements for plumbing fixture counts within cu

Preliminary Design Report



Zilker Clubhouse

Initial Structural Evaluation

Prepared for:

Limbacher & Godfrey Architects 2124 E. 6th Street, #102 Austin, Texas 78702



SPARKS ENGINEERING, INC.

FEBRUARY 3, 2020

Public Engagement Survey

Zilker Clubhouse Rehabilitation

Survey to Vendors and Renters

Project Engagement


PARTICIPANTS


72


- RESPONSES 651


COMMENTS 328


- Would a dedicated "Green Room" where a bride or groom could get dressed and prepped or other "back of house" area improve the function of the Zilker Clubhouse as an event venue?
- The Clubhouse is a historic facility and therefore is not air conditioned in the Main Hall. Based on your experience in the space, please position the slider to identify how strongly you feel.
- There is a grassy lawn on the north side of the building. Would improvements to this lawn area enhance future experiences at this site?















LEGEND


CLUBHOUSE

RANGERS





OPEN HOUSE | November 10, 2020 | 4








OPEN HOUSE | November 10, 2020 | **15**










Existing



Proposed



























SECTION thru MECH CLOSET





EXISTING CLUBHOUSE AND TERRACE

.•

•

0




































LOOKOUT POINT







PROPOSED SITE PLAN May 1, 2020


OPEN HOUSE | November 10, 2020 **31**














Zoysia Sod
540'0"
Blackfoot Daisy
Texas Lantana
White Mistflower
Inland Sea Oats Twistleaf Yucca
Eviating Codes Elm
Existing Cedar Elm
Big Muhly
VING FORM
20'
Mealy Blue Sage
Trailing Rosemary
1
Red Buckeye
Turk's Cap White Mistflower

PLANTING PALETTE



Texas Lantana

Lantana Urticoides



Rosemary

Rosmarinus officinalis



Red Buckeye Aesculus pavia var. pavia

White Mistflower

Ageratina havanensis











Seep Muhly Muhlenbergia reverchonii Vasey &





Big Muhly Muhlenbergia lindheimeri

Bull Muhly Muhlenbergia emersleyi




Sotol

Inland Seaoats

Chasmanthium latifolium







Cherokee Sedge Carex cherokeensis



Mealy Blue Sage Salvia farinacea 'Henry Duelberg'



Spanish Dagger Yucca gloriosa



Trailing Rosemary Rosmarinus officinalis 'prostratus'



American Beautyberry Callicarpa americana



Turk's Cap Malvaviscus arboreus var. drummondii



ZILKER BUILDING AND SITE PLAN PLANTING PLAN 2020 MAY 13



Switchgrass Panicum virgatum 'Shenandoah'



Narrow Leaf Yucca Yucca angustissima



Twistleaf Yucca Yucca rupicola



Blackfoot Daisy Melampodium leucanthum



ASAKURA ROBINSON

Current Schedule

- Design Development 10/2020 to 1/2021
- Construction Documents 2/2021 to 6/2021
- Bidding and Contract Award 7/2021 to 1/2022
- Construction 2/2022 to 10/2022

)2| |/2022

Thank You

More project information is available at: www.austintexas.gov/department/zilker-clubhouse-rehabilitation

> Contact Project Manager with questions at: HistoricAustinParks@austintexas.gov



Zilker Clubhouse, 1942, Foster, William Hague. University of North Texas Libraries, The Portal to Texas History, https://texashistory.unt.edu; crediting Austin Presbyterian Theological Seminary